

# LASER PREMIUM SYSTEM PROCESS CHART FOR ALL PAINT SYSTEMS

## **PERFECT CUT**

ALL IN ONE COMPOUND



AND



An easy to use "one for all" polishing compound

Keeps its cutting edge due to **SELF-SHARPENING PARTICLE TECHNOLOGY** 

Removes sanding marks up to P1500

Can be used on large surfaces

Suitable for all modern types of paint

Used for both the cutting- and the finish stage by simply changing the polishing pad

Contains no silicone or wax, polishing out instead of filling scratches



Art. No. 49911 Art. No. 49901



500 g

1 ka

# **PERFECT FINISH**

ANTI HOLOGRAM/SWIRL



A dedicated swirl remover for a professional finish

Removes swirl marks in a quick and effective manner

Specially designed to give the finishing touch to dark colored paint coats

Easy application and wipe-down

Contains no silicone or wax, polishing out instead of filling scratches



Art. No. 49902 500 q

# **PERFECT SHINE**

SHINE+PROTECT



The perfect product to bring the luster back to any cars paint job

Provides a quick and lasting shine

Will form a durable, water repellant layer that gives excellent protection and still allows fresh paint to breathe

Good filling capabilities help remove light holograms for a flawless finish



Art. No. 49903 500 ml

### **STAGE 1: CUT**



# **APPLICATORS**

Polishing Pad very hard or hard



Attach a very hard or hard polishing pad to a polisher



Shake bottle well before use



Dispense a small quantity of product onto surface or pad



Compound at 1500-1800 rpm



Wipe clean with a Finishing Cloth

## **STAGE 2:** FINISH



#### **APPLICATORS** Polishing Pad soft



Attach a soft polishing pad to a polisher



Shake bottle well before use



Dispense a very small quantity of product onto surface or pad



Compound at 1500-1800 rpm



Wipe clean with a Finishing Cloth

## **STAGE 2:** FINISH



#### **APPLICATORS** Polishing Pad soft



Attach a soft polishing pad to a polisher



Shake bottle well before use



Dispense a small quantity of product onto surface or pad



Start slowly compounding at 1000 rpm Slowly increase speed to 2000 rpm DO NOT ALLOW TO DRY



Wipe clean with a Finishing Cloth

## **STAGE 3:** PROTECT (for fresh paint)



#### **APPLICATORS** Polishing Pad soft



Attach a soft polishing pad to a polisher



Shake bottle well before use



Dispense a small quantity of product onto surface or pad



Compound at 1000-1500 rpm



Wipe clean with a Finishing Cloth